



23.08.2007 – Mould removed from area



28.08.2007 – Surface modelling of pond bottom



12.09.2007 – Construction of polder



20.09.2007 Moulding up the bank



20.09.2007 – 3 polders constructed



30.10.2007 - Drainpipe cleaning access in the foreground



30.10.2007 – Outflow grating for optional filter by-pass in the foreground



30.10.2007 – Construction of outflow structure



08.11.2007 – Vertical filters and horizontal filter planted with reed



04.12.2007 - Construction of inflow structures in the background



04.12.2007 – Construction of Inflow structure



04.12.2007 – Flow meter in Inflow structure



04.12.2007 – Piping, flow meters and valves in outflow structure



15.01.2008 – Valve- and flow meter structure (Inflow structure)



15.01.2008 – Pond receiving storm water runoff



15.01.2008 – View over pond from the nearest residential area