



08.08.2007 – Mould removed from area



21.08.2007 – Earthwork in progress



11.09.2007 – Excavated to Pond bottom level



13.09.2007 Construction of clay membrane





27.09.2007 – Moulding up the banks



29.09.2007 – Construction of inflow structure



06.10.2007 – Sand filters constructed



23.10.2007 – Bedding plants delivered





11.10.2007 – Inflow structure near completion



11.10.2007 – Inflow structure, stainless steel pipe installation




01.11.2007 – Planting of bedding plants



01.11.2007 Vertical sand filter





14.11.2007 – Flow meter structure, outlet from filters



14.11.2007 – Structures for handling outlets from various sections



26.01.08 – Facility completed except minor finish improvements



26.01.2008 Sampler structure

